

Inspection Photos
Operator: BP America
API: 067-07204
Date: 8/11/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, sand dropseed, and scattered ponderosa pine trees.



Photo 3. View of reference area comprised of ponderosa pine woodland with gambel oak understory, along with grasses and forbs such as sandberg bluegrass and yarrow.