


**Inspection Photos**  
**Operator: BP America**  
**API: 067-06507**  
**Date: 8/11/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, and rubber rabbitbrush.



Photos 3/4. View of musk thistles within the project area in flowering/seedling vegetative condition.



Photo 5. View of reference area comprised of ponderosa pine woodland and gambel oak shrubland, with a mosaic of sagebrush shrubland and open grassland comprised of fringed sage, black sage, smooth brome, and western wheatgrass.