

Inspection Photos
Location Name: Showers 5-4
Location ID: 330961



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Showers 5-4
Location ID: 330961




Photo 3 – Unused Downhole Pump, Stained Soil




Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Showers 5-4
Location ID: 330961



Photo 5 – Stained Soil



Photo 6 – Unused Tank