

Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 1 – Pumping Unit




Photo 2 – Stained Soil at Pumping Unit



Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520




Photo 3 – Stained Soil at Pumping Unit



Photo 4 – Crude Oil Tank



Inspection Photos
Location Name: Arthur Sheetz 1
Location ID: 317520



Photo 5 – Heater Treater, Produced Water Skim Tanks