

Inspection Photos
Location Name: Sievers 1-3-7-62
Location ID: 431322



Photo 1 – Pumping Unit, Weeds



Photo 2 – Tank Battery, Weeds

Inspection Photos
Location Name: Sievers 1-3-7-62
Location ID: 431322



Photo 3 – Weeds in the Reclamation Area



Photo 4 – Weeds in the Reclamation Area

Inspection Photos
Location Name: Sievers 1-3-7-62
Location ID: 431322



Photo 5 – Weeds in the Reclamation Area