

Inspection Photos

Location Name: Wolf Creek Unit 9

Location ID: 314168 & Spill/Release ID: 477240

Inspection Date: July 27, 2020



Location sign.



Stockpiled soil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Wolf Creek Unit 9

Location ID: 314168 & Spill/Release ID: 477240

Inspection Date: July 27, 2020



Note the trash and debris located within the excavation.



Note the trash and debris located within the excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources