

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334733



3" riser and flowline at wellhead to separator



3" riser and flowline removed at wellhead and being compacted back fill

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334733



3" flowline from wellhead to separator in process of being removed



Two risers were left on the backside of separators; they are part of a active manifold system. Dump line and sales line