

Inspection Photos
Operator: BP America
API: 067-08323
Date: 8/11/2020



Photo 1. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 2. View of musk thistles within the eastern project area. Approximately 150 individuals observed.



Photos 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of pinyon juniper woodland/gambel oak shrubland with understory of western wheatgrass, Arizona fescue, and *Heterotheca villosa*.