

Inspection Photos

Location Name: Yellow Creek Bridge Gas Plant

Facility ID: 434309 & Spill/Release ID: 477401

Inspection Date: July 28, 2020



Spill/Release location, photo taken from Co Rd 20.



Stockpiled material from the excavation, note the fluids and areas where the impacted material is not properly stored on the liner material.



Inspection Photos

Location Name: Yellow Creek Bridge Gas Plant

Facility ID: 434309 & Spill/Release ID: 477401

Inspection Date: July 28, 2020



Excavation looking east, note the stained soils on the sidewalls and bottom of the excavation.



Stockpiled hydrovac material



Inspection Photos

Location Name: Yellow Creek Bridge Gas Plant

Facility ID: 434309 & Spill/Release ID: 477401

Inspection Date: July 28, 2020



Stockpiled material, hydrocarbon odor present at time of inspection.

