

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913



Photo 3 WH sign

Photo 4 WH

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913



Photo 5 WH sign

Photo 6 WH

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913



Photo 7 TB signs

Photo 8 TB

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913




Photo 9 Horizontal Heated Separator

Photo 10 ECDs

Inspection Photos
Location Name: Cirbo 6-4-5
Location ID: 332913



Colorado Oil & Gas Conservation Commission
 7813 County Rd 24, Longmont, CO 80504, USA
 40.16638, -104.91192, 4821.7ft, 29°
 08/13/2020 12:58:32



Colorado Oil & Gas Conservation Commission
 7813 County Rd 24, Longmont, CO 80504, USA
 40.16637, -104.91187, 4821.4ft, 29°
 08/13/2020 12:59:10

Photo 11 Gas Meter Run

Photo 12 card in meter house indicates current calibration