

# Inspection Photos

API: 063-06045

Operator: CITATION OIL & GAS CORP

Inspection Date: 8/11/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020

## Inspection Photos



**Photo 1.** Facing northwest toward the location. The meter shed still remains at the location and the area is being farmed around where equipment remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020

## Inspection Photos



**Photo 2.** Facing west toward the location. The meter shed and pipe riser still remain which is interfering with farming operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020



## Inspection Photos



**Photo 3.** A pipe riser remains at Lat/Long:39.07978,-102.38848.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020

## Inspection Photos



**Photo 4.** The meter shed remains at the location which is interfering with farming operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020



## Inspection Photos



**Photo 5.** Facing northeast toward the meter shed. All equipment should have been removed within 3 months of plugging the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 063-06045 | Date: 8/11/2020