

Inspection Photos

API: 063-06292

Operator: CITATION OIL & GAS CORP

Inspection Date: 8/11/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 063-06292 | Date: 8/11/2020

Inspection Photos



Photo 1. Facing north near he location. This pipe riser still remains which is interfering with farming operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06292 | Date: 8/11/2020

Inspection Photos



Photo 2. The pipe riser remains at Lat/Long:39.05715,-102.43314.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06292 | Date: 8/11/2020

Inspection Photos



Photo 3. Facing north at the location. Pipe riser can be seen in upper left of photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06292 | Date: 8/11/2020

Inspection Photos



Photo 4. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06292 | Date: 8/11/2020