

Inspection Photos

API: 063-06049

Operator: CITATION OIL & GAS CORP

Inspection Date: 8/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 1. This is a 2016 aerial image of the location. There are multiple areas of disturbance shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 2. Facing northeast toward the access road. There is various equipment that remains along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 3. There is various equipment and pipe risers that remain approximately 700 ft. southwest of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 4. Facing north toward equipment that remains southwest of the location.



Inspection Photos



Photo 5. The fence around the equipment is degraded and the equipment appears to be left unused.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 6. There is unused pipe risers and equipment that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 7. Facing northeast along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 8. There is a meter shed that remains approximately 250 ft. east of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 9. Facing south toward the meter shed that has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 10. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020

Inspection Photos



Photo 11. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 063-06049 | Date: 8/11/2020