



39.97354, -109.04269, 5993.3ft, 287°
08/13/2020 11:22:37 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Maegher 11-12

API: 05-103-10439

Inspection: 700402884



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Tank, separator.

Maegher 11-12

API: 05-103-10439

Inspection: 700402884



39.97411, -109.04321, 5976.0ft, 242°
08/13/2020 11:25:35 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Unused pump jack.

Maegher 11-12

API: 05-103-10439

Inspection: 700402884



39.97419, -109.0432, 5965.5ft, 273°
08/13/2020 11:25:48 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Maegher 11-12

API: 05-103-10439

Inspection: 700402884