

Inspection Photos

8/13/2020

Operator: D & D RESOURCES INC - 22315

Location ID: 315255

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315255



Photo 1: Photo taken from the Location, facing east. Photo shows well marker, and utility equipment remaining on the Location.



Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315255



Photo 2: Photo taken from the east end of the Location, facing northeast. Photo shows large bare areas where stained soils are evident.



Inspection Photos
Operator Name: D & D RESOURCES INC - 22315
Location ID: 315255



Photo 3: Continued from photo 2.

