

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402354406

Date Received:  
03/27/2020

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Michael Cugnetti

720-845-6901

mcugnetti@verdadresources.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696301538

Inspection Date: 03/10/2020

FIR Submit Date: 03/10/2020

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

**LOCATION - Location ID: 423699**

Location Name: Dietzler Number: 10-9-60 PAD County: WELD

Qtrqr: SWS Sec: 10 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.758020 Longitude: -104.087250

**FACILITY - API Number: 05-123-00 Facility ID: 423698**

Facility Name: Dietzler Number: 10-14-9-60

Qtrqr: SWS Sec: 10 Twp: 9N Range: 60W Meridian: 6

Latitude: 40.758020 Longitude: -104.087250

**CORRECTIVE ACTIONS:**

1 ☒ CA# 137092

Corrective Action: Comply With Rule 210.d

Date: 03/25/2020

Response: CA COMPLETED

Date of Completion: 03/24/2020

Operator: PW water tank labelled with NFPA label, contents and capacity.  
Comment: Oil tanks labelled with Contents and Capacity.  
Please see attached 2 photos for documentation of corrective actions.

COGCC Decision: Approved

COGCC Representative: Approved

2 ☒ CA# 137093

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 03/25/2020

Response: CA COMPLETED

Date of Completion: 03/24/2020

Operator Comment: Stained soil removed and properly disposed of.  
Please see photo documentation attached.

COGCC Decision: Approved

COGCC Representative: Approved

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 3/27/2020 11:11:07 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402354406	FIR RESOLUTION SUBMITTED
402354431	PW tank CA Photo Documentation
402354434	Oil tank CA photo Documentation
402354436	Stained soil CA photo documetation

Total Attach: 4 Files