

# *Inspection Photos*

*Loc#335188*

*Operator: Terra*

*Inspection Number: 692402426*

*Inspection Date: 7/31/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location and repaired Cut.

July 31, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra McBurney Loc#324234



Photo#2:  
Equipment at base of Cut has been removed.



Photo#3:  
Fill slope.

July 31, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Terra McBurney Loc#324234