

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402361339

Date Received:

04/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

NBL_DJBU_Inspections@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 696301584

Inspection Date: 03/18/2020

FIR Submit Date: 03/18/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 437863

Location Name: LD Number: 12 Tank County: _____

Qtrqr: NENW Sec: 12 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.771960 Longitude: -103.815390

FACILITY - API Number: 05-123-00 Facility ID: 437863

Facility Name: LD Number: 12 Tank

Qtrqr: NENW Sec: 12 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.771960 Longitude: -103.815390

CORRECTIVE ACTIONS:

1 ☒ CA# 137288

Corrective Action: Comply with Rule 210.c. and 210.d.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/01/2020

Operator Comment: Noble installed the missing signs and labels.

COGCC Decision: Approved pending re-inspection

Approved pending Re-Inspection

COGCC
Representative:

2 ☒ CA# 137289

Corrective Action: Comply with Rule 603.f.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble removed the unused equipment from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

3 ☒ CA# 137290

Corrective Action: Comply with Rule 603.f. for the Unused Supply and Unmarked Riser.
For localized stained soils - Properly dispose of oily waste in accordance with 907.e.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble removed the unused supply from location.
Noble cleaned up the soil near the shed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

4 ☒ CA# 137291

Corrective Action: Comply with Rule 603.f.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble covered the the trash dumpster and picked up all the trash on location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

5 ☒ CA# 137292

Corrective Action: Comply with Rule 603.f.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble removed the unused equipment from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

6 ☒ CA# 137293

Corrective Action: Comply with Rule 603.f.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment:	Noble removed the unused equipment from location.
COGCC Decision:	Approved pending re-inspection
COGCC Representative:	Approved pending Re-Inspection

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Kimberly Mollenhauer	Signed: _____
Title: EHS Tech	Date: 4/3/2020 9:04:59 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402361339	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files