

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402366084

Date Received:

04/09/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

NBL_DJBU_Inspections@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 696301634

Inspection Date: 03/31/2020

FIR Submit Date: 04/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 433197

Location Name: ROHN STATE Number: LD10-65HN County: _____

Qtrqr: NESE Sec: 9 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.764520 Longitude: -103.861110

FACILITY - API Number: 05-123-00 Facility ID: 433197

Facility Name: ROHN STATE Number: LD10-65HN

Qtrqr: NESE Sec: 9 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.764520 Longitude: -103.861110

CORRECTIVE ACTIONS:

1 ☒ CA# 137644

Corrective Action: Comply with Rule 210.c. and 210.d.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: Noble installed the signs and labels on location.

COGCC Decision: Approved pending re-inspection

Approved pending Re-Inspection

COGCC
Representative:

2 ☒ CA# 137645

Corrective Action: Comply with Rule 210.c. and 210.d.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble installed the signs and labels on location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

3 ☒ CA# 137646

Corrective Action: Comply with Rule 210.d.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble installed the signs and labels on location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

4 ☒ CA# 137647

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator
Comment: Noble treated the stained soil near the compressor drain pit.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending Re-Inspection

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kimberly Mollenhauer

Signed: _____

Title: EHS TEch

Date: 4/9/2020 6:30:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402366084	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files