

Inspection Photos

Location Name: 70 RANCH USX BB-65N63W /17SENW

Location #: 310256



Colorado Oil & Gas Conservation Commission
40.40135, -104.46356, 4610.5ft, 275°
06/10/2020 14:32:30

Photo #1

70 Ranch USX BB 17-19 (05-123-26144)

Abandoned Location | AL

~ 210 yds.

*No disturbance or evidence of oil & gas activity
prior insp.*