

Inspection Photos
Location Name: Montgomery 1-27
Location ID: 332747



Wellhead

Inspection Photos
Location Name: Montgomery 1-27
Location ID: 332747



Stained soil on 7/6/2020



Stained soil on 8/14/2020

Inspection Photos
Location Name: Montgomery 1-27
Location ID: 332747



Unused equipment on 7/6/2020



Unused equipment on 8/14/2020