

Inspection Photos
Operator: BP America
API: 067-06725
Date: 8/13/2020



Photo 1. View of the project area from the southern edge of the working area facing center.



Photo 2. View of the western fill slope facing northward. Revegetation is progressing with rubber rabbitbrush, crested wheatgrass, and smooth brome.



Photo 3. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, and forbs such as snakeweed.