


**Inspection Photos**  
**Location Name: Dechant State V 16-3JI**  
**Location ID: 330853**



**Photo 1 WH sign**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Dechant State V 16-3JI**  
**Location ID: 330853**



**Photo 3 TB sign**

**Photo 4 TB**

**Inspection Photos**  
**Location Name: Dechant State V 16-3Jl**  
**Location ID: 330853**



**Photo 5 Horizontal Heated Separator**




**Photo 6 ECD**



**Inspection Photos**  
**Location Name: Dechant State V 16-3J1**  
**Location ID: 330853**



**Photo 7 Gas Meter Run**



**Photo 8 Card in meter house indicates that calibration is not current**