



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 700402952



40.15023, -108.2037, 6331.8ft, 38°
08/17/2020 03:17:56 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Separator.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 700402952



40.15037, -108.20369, 6320.2ft, 160°
08/17/2020 03:18:46 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 700402952



40.15041, -108.20377, 6327.0ft, 65°
08/17/2020 03:18:34 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Storage building.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 700402952



40.1504, -108.20362, 6320.9ft, 293°
08/17/2020 03:18:58 PM



40.15052, -108.20392, 6334.5ft, 43°
08/17/2020 03:19:40 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tanks.

Ant Hill Unit 7-43

API: 05-103-10992

Inspection: 700402952