

Inspection Photos

Location Name: Raymond V. Sarchet B 2

Location ID: 319234



Photo 1 WH sign

Photo 2 WH



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Raymond V. Sarchet B 2
Location ID: 319234



Photo 3 Weeds overgrown along access road and ROW



Photo 4 Weeds overgrown around location ROW

Inspection Photos
Location Name: Raymond V. Sarchet B 2
Location ID: 319234



Photo 5 ECD



Photo 6 Horizontal Heated Separators

Inspection Photos
Location Name: Raymond V. Sarchet B 2
Location ID: 319234



**Photo 7 Gas Meter Run, Door stuck closed on housing,
Calibration is unknown at time of inspection.**

Photo 8 TB signs

Inspection Photos
Location Name: Raymond V. Sarchet B 2
Location ID: 319234



Photo 9 TB