

BP L48 San Juan



V2 Compliance Follow Up Form

18151534718

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200814-18151534718

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 14, 2020 12:39:16 PM MDT

394 Hawks Meadow Dr, Bayfield, CO 81122, USA

Aug 14, 2020 12:36:58 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 11, 2020
Well Name	GOEGLEIN GAS UNIT 2
API Number	50670899100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris Clean Up Contaminated Soils Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stains

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Installed diversion ditch

Photo of fourth corrective action completed



Completed work description

Erosion repair

Completed work description of corrective action 4

Installed rock run down

Additional photos



Additional photos



Additional photos

**Summary of all work completed**

Compliance, installed rock run down, cleaned up stains , installed diversion ditch fixed erosion , picked up trash and installed new equipment sign