

Inspected Facilities

Facility ID: 89216 Type: WELL API Number: 071-06796 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP TO INSPECTION DOC#695102935. BASED ON PHOTOS SUBMITTED BY OPERATOR ON FIRR DOC#40243536, CA'S HAVE BEEN ADDRESSED.	beardsit	08/19/2020