

Final Reclamation Inspection

August 13, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319166

Inspection Document #: 697501887

Weld County, CO

SESE Section 27 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 22 PAN AM C #2
Location ID: 319166



Photo 1. Photo taken from the well location, facing West. Photo illustrates the Operator has recently performed final reclamation activities. The associated tank battery, soon in the background, is still in use for other nearby wells.



Inspection Photos
Location Name: UPRR 22 PAN AM C #2
Location ID: 319166



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.

