

Final Reclamation Inspection

August 13, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 331965

Inspection Document #: 697501889

Weld County, CO

SESE Section 27 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 1. Photo taken from the northern well location access road, facing South. Photo illustrates the Operator has recently performed final reclamation activities. Germination was sparse throughout the access road and well location. Annual, weedy growth was observed throughout portions of the access road.



Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 1. Photo taken from the central well location access road, facing South. Photo illustrates annual, weedy growth. Operator will likely need to perform ongoing weed management to suppress annual, weedy growth to allow for successful germination and establishment of perennial species.



Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 3. Photo taken from the southern well location access road, facing South. See comments under Photo 1.



Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 4. Photo taken from the northwestern well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 5. Photo taken from the central well location, facing Southeast. See comments under Photo 1.



Inspection Photos
Location Name: BARCLAY #16-27
Location ID: 331965



Photo 6. Photo taken from the central well location, facing North. See comments under Photo 1.

