

## Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-610S90W /34NWSW

Location ID: 324463



**Photo #1751 from entrance to location**



**Photo #1752 from entrance to location**



## Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-610S90W /34NWSW

Location ID: 324463



**Photo #1754 Tank capacity not labeled.**



**Photo #1753 Unused equipment in tank containment.**