

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 8/18/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos




Photo 1. Facing southwest along the main road. It appears that some noxious weeds were controlled along the road but there more that will need additional control. The red arrow shows the pipeline area along the road which this area will also need to be monitored for weed control.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos



Photo 2. Facing west along the road ascending the hill. The road appears to be stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos



Photo 3. Facing west along the road ascending the hill. There are noxious weeds which have not been controlled along the roadway. Red arrow points to List B noxious weed Hounds tongue.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos



Photo 5. There are numerous noxious weeds along the cut slope that have not been controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020

Inspection Photos



Photo 6. It appears the Canada thistle noxious weeds have been controlled this season along the cut slope however, the Hounds tongue has not been controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 8/18/2020