

Inspection Photos

Operator: Great Western Operating Company LLC - 10110

Lease: Weco P Dechant 42-28 #1

Facility ID/API, 207955 / 05-017-06890



1. Battery area ripped and contoured



2. Battery area ripped and contoured



Inspection Photos

Operator: Great Western Operating Company LLC - 10110

Lease: Weco P Dechant 42-28 #1

Facility ID/API, 207955 / 05-017-06890



3. Meter and riser have not been removed, (Tumbleweed Midstream)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources