

**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 1 – Wellhead Sign**




**Photo 2 – Gas Lift Meter Shed, Weeds**





**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 3 – Tank Battery, berm not sufficient, weeds**



**Photo 4 – Tank Battery, weeds**



**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 5 – Separator, weeds**



**Photo 6 – Gas Meter, No Current Calibration card**



**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 7 – Pumping Unit**



**Photo 8 – Stained Soil at Wellhead**



**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 9 – Pumping Unit, Weeds**




**Photo 10 – Stained Soil at Gas Engine**





**Inspection Photos**  
**Location Name: Anne State 6**  
**Location ID: 326750**



**Photo 11 – Stained Soil at Gas Engine**