

**Inspection Photos**  
**Location Name: Vera 1**  
**Location ID: 318556**




**Photo 1 – Separator and Gas Meter House, Weeds**



**Photo 2 – Tank Battery, Weeds**

**Inspection Photos**  
**Location Name: Vera 1**  
**Location ID: 318556**




**Photo 3 – Gas Meter, No Current Calibration card**




**Photo 4 – Pumping Unit, Weeds**



**Inspection Photos**  
**Location Name: Vera 1**  
**Location ID: 318556**



**Photo 5 – Unmarked Risers at Separator, Weeds**



**Photo 6 – Unmarked Risers at Separator, Weeds**