

Inspection Photos
Location Name: Seyfried 2
Location ID: 327613



Photo 1 – Pumping Unit, Stained Soil



Photo 2 – Pumping Unit, Weeds

Inspection Photos
Location Name: Seyfried 2
Location ID: 327613



Photo 3 – Temp Tank connected to the Wellhead