

Inspection Photos
Location Name: Seyfried 2 TB
Location ID: 470277



Photo 1 – Tank Battery, Weeds



Photo 2 – Unused Heater Treater



Inspection Photos
Location Name: Seyfried 2 TB
Location ID: 470277



Photo 3 – Separator, Weeds




Photo 4 – Gas Meter – No current Calibration Card on Site, Weeds



Inspection Photos
Location Name: Seyfried 2 TB
Location ID: 470277



Colorado Oil and Gas Conservation Commission
40.24939, -104.27479, 4550.1ft, 158°
08/17/2020 13:33:02

Photo 5 – Berms are inadequate