

**Inspection Photos**  
**Location Name: Parmlee 3**  
**Location ID: 327613**



**Photo 1 – Pumping Unit, Weeds**



**Photo 2 – Pumping Unit and Temp Tank, Weeds**

**Inspection Photos**  
**Location Name: Parmlee 3**  
**Location ID: 327613**



**Photo 3 – Stained Soil at Wellhead, Weeds**