

Inspection Photos
Location Name: Parmlee 3 TB
Location ID: 470289



Photo 1 – Heater Treater



Photo 2 – Produced Water Tank – Content, Capacity and NFPA Labels have faded

Inspection Photos
Location Name: Parmlee 3 TB
Location ID: 470289



Colorado Oil and Gas Conservation Commission
40.25663, -104.27513, 4554.6ft, 180°
08/17/2020 13:46:22

Photo 3 – Gas Meter appears not be updated on Calibration.



Colorado Oil and Gas Conservation Commission
40.25675, -104.27568, 4513.1ft, 188°
08/17/2020 13:47:38

Photo – Unmarked Riser at Crude Oil Tanks

