

Inspection Photos
Location Name: Sydney Strear #6
Location ID: 318347



Photo 1 WH sign

Photo 2 Stained soil around WH

Inspection Photos
Location Name: Sydney Strear #6
Location ID: 318347



Photo 3 Weeds overgrown at location entrance

Photo 4 electric panel, meter box and transformers

Inspection Photos
Location Name: Sydney Strear #6
Location ID: 318347



Photo 5 stained ground at base of pump jack

Photo 6 leaking seal on pump jack gear box

Inspection Photos
Location Name: Sydney Strear #6
Location ID: 318347



Photo 7 stained ground at base of pump jack

Photo 8 leaking seal on pump jack gear box

Inspection Photos
Location Name: Sydney Strear #6
Location ID: 318347



Photo 9 stained soil around WH