

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2020

Submitted Date:

08/20/2020

Document Number:

696103581**FIELD INSPECTION FORM**Loc ID 305307 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nbl energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276481	WELL	PA	03/29/2019	OW	123-22778	FOSS 13-11	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.493264, -104.497986

Abandoned Centralized Battery formerly served 5 Location IDs (310603, 305308, 305307, 305309, 305265).
 (Well(s): 2: Temporarily Abandoned | TA ; 3: Plugged & Abandoned | PA).

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

0

Comment:

Plugged & Abandoned | PA.
Battery Abandoned.
ALL equipment removed.

Corrective Action:

Date:

Type: Emission Control Device

0

Comment:

Plugged & Abandoned | PA.
Battery Abandoned.
ALL equipment removed.

Corrective Action:

Date:

Type: Horizontal Heated Separator

0

Comment:

Plugged & Abandoned | PA.
Battery Abandoned.
ALL equipment removed.

Corrective Action:

Date:

Type: Pig Station

0

Comment:

Plugged & Abandoned | PA.
Battery Abandoned.
ALL equipment removed.

Corrective Action:

Date:

Type: Gas Meter Run

0

Comment:

Plugged & Abandoned | PA.
Battery Abandoned.
ALL equipment removed.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:



Inspected Facilities

Facility ID: 276481 Type: WELL API Number: 123-22778 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 08/20/2020 at approximately 13:23 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: FOSS-66N64W /13NENE Location ID: 305307 Well Name: Foss 13-11 API: 05-123-22778 Location County: Weld County, Colorado Weather: Overcast w/ haze, dry. While there, I observed:</p> <p>Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.493264, -104.497986</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (310603, 305308, 305307, 305309, 305265). (Well(s): 2: Temporarily Abandoned TA ; 3: Plugged & Abandoned PA).</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #402054443 indicates plugging, cut/cap date: 03/28/2019. Approved.</p> <p>PA well photo from prior insp.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103582	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229261