

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2020

Submitted Date:

08/21/2020

Document Number:

700701376

FIELD INSPECTION FORM

Loc ID 334642 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 271436 | WELL | PR | 07/27/2006 | GW | 045-09884 | PARADISE 11-8B (B11BW) | PR |
| 271438 | WELL | PR | 06/17/2006 | GW | 045-09882 | PARADISE 11-2B (B11BW) | PR |
| 271440 | WELL | SI | 09/01/2019 | GW | 045-09881 | PARADISE 11-1B (B11BW) | SI |
| 272962 | WELL | PR | 06/12/2006 | GW | 045-10198 | PARADISE 11-2C (B11BW) | PR |
| 274452 | WELL | PR | 05/19/2006 | GW | 045-13349 | PARADISE 11-7A (B11BW) | PR |
| 274453 | WELL | PR | 06/16/2006 | GW | 045-13350 | PARADISE 11-3A (B11BW) | PR |

General Comment:[COGCC Inspection Report Summary](#)

On Friday 8/21/20 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B11BW, at Location # 334642 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|-----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--------|--|-------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|-----------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | |
|-----------------------|--|-------|
| Type: Gas Meter Run | # 7 | |
| Comment: | All meters calibrated on location within a year. | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|-----------|---------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | shared containment with condensate tanks | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | |
|--|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>271436</u> | Type: <u>WELL</u> | API Number: <u>045-09884</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: <u>271438</u> | Type: <u>WELL</u> | API Number: <u>045-09882</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: <u>271440</u> | Type: <u>WELL</u> | API Number: <u>045-09881</u> | Status: <u>SI</u> | Insp. Status: <u>SI</u> |
| Idle Well | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | |
| Comment: <u>last produced 8/1/2019</u> | | | | |
| Corrective Action: | | | | Date: _____ |
| Facility ID: <u>272962</u> | Type: <u>WELL</u> | API Number: <u>045-10198</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: <u>274452</u> | Type: <u>WELL</u> | API Number: <u>045-13349</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: <u>274453</u> | Type: <u>WELL</u> | API Number: <u>045-13350</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | Culverts | | | | |
| Gravel | | Ditches | | | | |
| | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 700701382 | photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229970 |