

## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



CE&P Facility ID: 287848, Gate entrance.

Sign from CR 46.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Entrance to CE&P Facility. Note: Gate is now secured and storm water runoff controls have been implemented. Looking at soil/material mound in the SE corner of the facility.



Entrance to CE&P Facility. Note: Gate is now secured and storm water runoff controls have been implemented.



## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Pea gravel stockpiles have been removed.



Trash and debris have been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Some trash and debris remain and operator has a maintenance plan in place for removal.



Storm water BMPs in place around soil stockpiles.



## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



One-inch PVC well removed and abandoned.



Northern stock pile looking east.

## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Section of fence repaired.



Gate closed and secured.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



**Evidence of sediment leaving the CE&P facility.**



**Various debris and stockpiles removed.**



## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Equipment has been removed.



Monitoring well has been abandoned.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 21, 2020



Storm water controls in place.



E&P waste impacted material removed.