



**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | IGNITOR/COMBUSTOR |       |  |
| Comment:           | barbwire          |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | SEPARATOR         |       |  |
| Comment:           | Barbwire          |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Panel             |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | TANK BATTERY      |       |  |
| Comment:           | Barbwire          |       |  |
| Corrective Action: |                   | Date: |  |

**Equipment:**

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 4 |       | corrective date |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Gas Meter Run   | # 1 |       |                 |

|                                   |                                   |  |       |
|-----------------------------------|-----------------------------------|--|-------|
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Plunger Lift                | # 1                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Horizontal Heated Separator | # 2                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Bradenhead                  | # 1                               |  |       |
| Comment:                          | Appears to be plumbed to surface. |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Pig Station                 | # 1                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |
| Type: Emission Control Device     | # 2                               |  |       |
| Comment:                          |                                   |  |       |
| Corrective Action:                |                                   |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS                |
|--------------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER     | 1 | 100 BBLs | FIBERGLASS AST |         | 40.286500,-104.486500 |
| Comment:           |   |          |                |         |                       |
| Corrective Action: |   |          |                |         | Date:                 |

Paint

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | #                                        | Capacity | Type        | Tank ID | SE GPS                |
|--------------------|------------------------------------------|----------|-------------|---------|-----------------------|
| PRODUCED WATER     | 1                                        | OTHER    | BV CONCRETE |         | 40.286500,-104.486500 |
| Comment:           | Shares containment with crude oil tanks. |          |             |         |                       |
| Corrective Action: |                                          |          |             |         | Date:                 |

Paint

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |

|                    |          |                     |                     |             |                       |  |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|--|
| Other (Type)       |          |                     |                     |             |                       |  |
| <b>Berms</b>       |          |                     |                     |             |                       |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |  |
|                    |          |                     |                     |             |                       |  |
| Comment:           |          |                     |                     |             |                       |  |
| Corrective Action: |          |                     |                     |             | Date:                 |  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |  |
| CRUDE OIL          | 2        | 300 BBLs            | STEEL AST           |             | 40.286500,-104.486500 |  |
| Comment:           |          |                     |                     |             |                       |  |
| Corrective Action: |          |                     |                     |             | Date:                 |  |
| <b>Paint</b>       |          |                     |                     |             |                       |  |
| Condition          | Adequate |                     |                     |             |                       |  |
| Other (Content)    |          |                     |                     |             |                       |  |
| Other (Capacity)   |          |                     |                     |             |                       |  |
| Other (Type)       |          |                     |                     |             |                       |  |
| <b>Berms</b>       |          |                     |                     |             |                       |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |  |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |  |
| Comment:           |          |                     |                     |             |                       |  |
| Corrective Action: |          |                     |                     |             | Date:                 |  |
| <b>Venting:</b>    |          |                     |                     |             |                       |  |
| Yes/No             | NO       |                     |                     |             |                       |  |
| Comment:           |          |                     |                     |             |                       |  |
| Corrective Action: |          |                     |                     |             | Date:                 |  |
| <b>Flaring:</b>    |          |                     |                     |             |                       |  |
| Type               |          |                     |                     |             |                       |  |
| Comment:           |          |                     |                     |             |                       |  |
| Corrective Action: |          |                     |                     |             | Date:                 |  |

**Inspected Facilities**

Facility ID: 283875 Type: WELL API Number: 123-23707 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment                                                                                                                                                                                                                                                                                                                                                                                                                                 | User   | Date       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>                     On Monday 8/24/20 at approximately 0959hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Spike State CC 30-19 of Noble Energy at Location ID: 305931 in Weld County, Colorado. While there, I observed a well that is SI, LO/TO. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p> | burnsa | 08/24/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL                                                                                                                                                                 |
|--------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699102293    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5230560</a> |