

Interim Reclamation and Stormwater Inspection

August 17, 2020

Operator: CUB CREEK ENERGY- #10542

Location ID: 446104

Inspection Document #: 697501906

Weld County, CO

NWSE Section 32 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MARKHAM /PAD
Location ID: 446104



Photo 1. Photo taken from the northeastern location, facing West. Photo illustrates the Operator sign with unmanaged weeds (Kochia and cheatgrass).

Inspection Photos
Location Name: MARKHAM /PAD
Location ID: 446104



Photo 2. Photo taken from the northeastern location, facing East. Photo illustrates unmanaged weeds (Kochia and cheatgrass) on either side of the main access road.



Photo 3. Photo taken from the northeastern location, facing South. Photo illustrates unmanaged weeds (Kochia) throughout the interim areas.

Inspection Photos
Location Name: MARKHAM /PAD
Location ID: 446104



Photo 4. Photo taken from the northeastern well pad, facing South. See comments under Photo 3.

Inspection Photos
Location Name: MARKHAM /PAD
Location ID: 446104



Photo 5. Photo taken from the northeastern well pad, facing West. See comments under Photo 3.

Note: stormwater BMPs appear to be in proper functioning condition.

Inspection Photos
Location Name: MARKHAM /PAD
Location ID: 446104



Photo 6. Photo taken from the northern well pad, facing West. See comments under Photo 5.