

**Inspection Photos**  
**Location Name: Bredehoft 1**  
**Location ID: 319977**



**Pic 1 Gas flaring from ECD**



**Pic 2**

**Inspection Photos**  
**Location Name: Bredehoft 1**  
**Location ID: 319977**



**Pic 3**

