

Inspection Photos

API: 071-06183

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/17/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06183 | Date: 8/17/2020

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06183 | Date: 8/17/2020

Inspection Photos



Photo 2. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06183 | Date: 8/17/2020

Inspection Photos



Photo 3. Facing south at the location. There are some bare areas that may need additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06183 | Date: 8/17/2020

Inspection Photos



Photo 4. Facing east at the location. There are some bare areas that may need additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06183 | Date: 8/17/2020