

Inspection Photos

API: 071-06436

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/17/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06436 | Date: 8/17/2020

Inspection Photos



Photo 1. There is a metal pipeline box near the location which the lid has blow off. This needs to be repaired to prevent wildlife entry.



Inspection Photos



Photo 2. Facing southeast toward the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06436 | Date: 8/17/2020

Inspection Photos



Photo 3. Facing northwest toward the reclaimed access road in the canyon bottom. There is some noxious weeds in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06436 | Date: 8/17/2020

Inspection Photos



Photo 4. Facing northeast toward the reclaimed access road in the canyon bottom.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06436 | Date: 8/17/2020