

Inspection Photos
Operator: Logos Operating
API: 067-05524
Date: 8/20/2020



Photo 1. View of the Logos well from the southern well pad entrance facing center. Dense kochia growing throughout the project area.



Photo 2. View of the well with kochia up to 5 feet tall growing around project equipment. Kochia will break and become debris.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of dense Russian knapweeds growing within the western project area.



Photo 5. View of reference area comprised of pinyon/juniper woodland vegetation with understory of shrubs and grasses/forbs such as antelope bitterbrush, mountain mahogany, Indian ricegrass and *Heterotheca villosa*.