

**Inspection Photos**  
**Operator: WPX Energy**  
**API: 067-05752**  
**Date: 8/18/2020**



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the western project area facing northwestward. Revegetation is progressing with needleandthread grasses, western wheatgrass, *Heterotheca villosa*, and sand dropseed.



Photo 3. View of the southern project area from the southwestern corner facing northeastward.



Photo 4. View of revegetation along the former access road.



Photo 5. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, needleandthread grass and forbs such as *Heterotheca villosa* and Townsend daisy.