

# *Inspection Photos*

*API#103-01081*

*Operator: Chevron*

*Insp #: 692402440*

*Insp Date: 8/5/2020*



**Photo#1:**  
Overview of Location to Northeast

August 5, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Chevron PA Wilson Creek Morrison Unit API#103-01081



Photo#2:  
View along pad to South.

August 5, 2020



Inspection Photos: Chevron PA Wilson Creek Morrison Unit API#103-01081



Photo#3:  
Dry hole Marker; view to North.

August 5, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#4:  
Dry hole Marker; view to South

Inspection Photos: Chevron PA Wilson Creek Morrison Unit API#103-01081



Photo#5:  
Concrete installation; view to East.



Photo#6:  
Concrete installation; view to Northwest.



Photo#7:  
Pipes/lines/riser daylighting from bank below pad.

August 5, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#8:  
Lines/pipes down gradient of site indicated by  
arrows.